


Form L Fig. 1

1 mm L


Step : 0.050° Cnt Time: 1.000 Sec.  
Range: 2.00 - 40.00 (Deg) Cnt. Scan Rate : 3.00 Deg/min.



Scan M FIG. 2

2 cm M

Range: 2.00 - 40.00 (Deg) Cont. Scan Rate: 3.00 Deg/min. Step: 0.050° Cont Time: 1.000 Sec.




form D FIG. 3

form P

Range: 2.00 - 40.00 (Deg) Cont. Scan Rate: 3.00 Deg/min.


Step: 0.050° Cont Time: 1.000 Sec.



# Form Q FIG. 4

1 cm Q


Step : 0.050' Cnt Time: 1.000 Sec.  
Range: 2.00 - 40.00 (Deg) Cont. Scan Rate : 3.00 Deg/min.



film 5 - FIG. 5

Met:

Range: 2.00 - 40.00 (Deg) Cnt Time: 1.000 Sec.  
Step: 0.050 (Deg) Cnt. Scan Rate: 3.00 Deg/min.



T4 - FIG. 6

